
# DELLORTO 40 DHLA
*Exploded view*




https://www.carbparts.eu
Priser og produkttilgængelighed kan ændres

# DELLORTO 40 DHLA

*Liste over dele*

| No | Varenr. | Pris | Stk. | Beskrivelse |
|---|---|---|---|---|
| 1 | 7956 | $ 18.8 | | DHLA 45/48 choke |
| 2 | 8383 | $ 17.4 | | DHLA 40 choke |
| 3 | 8011 | $ 39.1 | | DHLA 45/48 Aux. Venturi |
| 4 | 7848 | $ 39.1 | | DHLA 40 Aux. Venturi |
| 5 | 7484 | $ 6.1 | | Main Jet |
| 6 | 7644 | $ 6.1 | | Idle jet |
| 7 | 7851 | $ 8.7 | | Pump jet |
| 8 | 3315 | - | | Starter jet |
| 9 | 7772 | $ 18.5 | | Main emulsion tube |
| 10 | 7482 | - | | Starter emulsion tube |
| 11 | 7485 | $ 6.1 | | Air corrector |
| 12 | 7850 | $ 13.2 | | Idle holder/emulsion tube |
| 13 | 8811 | $ 14.5 | | Needle valve, metal tipped |
| 14 | 7481 | - | | Throttle butterfly DHLA 40 |
| 15 | 7298 | $ 31.8 | | Float assy |
| 16 | 7501 | $ 16.6 | | Choke piston cover bolt |
| 17 | 7413 | $ 6.6 | | Choke piston spring |
| 18 | 9609 | - | | Choke piston |
| 19 | 6434 | $ 2.1 | | Choke outer cable clamp screw |
| 20 | 7488 | $ 19.3 | | Choke cable support |
| 21 | 9818 | - | | Top cover casting |
| 22 | 9358 | $ 5.4 | | Top cover casting gasket |
| 23 | 9498 | - | | Needle valve filter |
| 24 | 7530 | $ 2.1 | | Vent cover screw |
| 25 | 7549 | $ 13.2 | | Vent cover |
| 26 | 6430 | $ 1.8 | | Top cover screw |
| 27 | 4997 | - | | Top cover spring washer |
| 28 | 7511 | $ 4.1 | | Vent cover gasket |
| 29 | 7062 | $ 9.1 | | Choke inner cable clamp |
| 30 | 6850 | $ 1.2 | | Cable clamp washer |
| 31 | 6432 | $ 8.3 | | Choke cable clamp nut |
| 32 | 7854 | $ 5.8 | | Choke cable return spring |
| 33 | 7838 | $ 8.7 | | Choke spring cup washer |
| 34 | 4957 | - | | Spring washer |
| 35 | 2906 | $ 1.2 | | Choke spring retaining nut |
| 36 | 9610 | $ 38.9 | | Choke actuator cam |
| 37 | 7837 | $ 1.2 | | Actuator cam spring washer |
| 38 | 9611 | - | | Actuator cam¨retaining bush |
| 39 | 7341 | $ 5.8 | | Choke actuator lever |
| 40 | 6425 | - | | Needle valve washer |
| 41 | 7503 | $ 2.2 | | Float assy pivot pin |
| 42 | 7663 | - | | Banjo fibre washer, inner |
| 43 | 8071 | $ 27.1 | | Fuel banjo, single 90 degree |
| 44 | 7661 | $ 47.2 | | Fuel banjo, double standard |
| 45 | 1419 | $ 6.4 | | Banjo fuel filter |
| 46 | 7662 | - | | Banjo fibre washer, outer |
| 47 | 7659 | $ 7.5 | | Banjo bolt |
| 48 | 7540 | - | | O ring |
| 49 | 7513 | $ 8.3 | | Cap screw |
| 50 | 7525 | $ 8.3 | | Pump jet weight |
| 51 | 6415 | $ 3.5 | | Pump jet ball bearing |
| 52 | 10747 | $ 15 | | Pump jet holder |
| 53 | 10748 | $ 6.3 | | Pump jet filter/spring |
| 54 | 6173 | $ 1.1 | | Pump jet O ring |

| No | Varenr. | Pris | Stk. | Beskrivelse |
|---|---|---|---|---|
| 55 | 6426 | - | | Pump jet cap fibre washer |
| 56 | 9926 | $ 9.9 | | Air bleed screw |
| 57 | 8678 | - | | Air bleed screw O ring |
| 58 | 7959 | $ 5.2 | | Vacuum blanking screw |
| 59 | 8857 | $ 11.1 | | G/H prog. blanking screw |
| 60 | 9656 | $ 13.8 | | Mixture screw 48/45/40H |
| 61 | 9336 | $ 2.2 | | Mixture screw spring |
| 62 | 8260 | - | | Mixture screw washer |
| 63 | 10381 | $ 24.6 | | DHLA late alfa lever |
| 64 | 9754 | $ 10.4 | | DHLA throttle stop screw |
| 65 | 6423 | $ 1.2 | | Spindle nut |
| 66 | 6581 | $ 1.8 | | Spindle nut lock washer |
| 67 | 10714 | $ 50.7 | | Short Lotus lever |
| 68 | 7958 | $ 3.6 | | Spindle end cover |
| 69 | 7537 | $ 2.6 | | Spindle washer |
| 70 | 7490 | $ 2.3 | | Spindle bearing |
| 71 | 7627 | $ 4.5 | | Pump rod spring |
| 72 | 8058 | - | | 40/45/48 E Pump Cover assy |
| 73 | 7625 | $ 5.5 | | Pump rod nut |
| 74 | 6390 | $ 1 | | Pump rod lock nut |
| 75 | 7626 | $ 4.2 | | Diaphagm Spring |
| 76 | 7515 | $ 13 | | Pump Diaphragm |
| 77 | 5011 | $ 1.1 | | Spring washer (pump cover) |
| 78 | 6429 | $ 1.6 | | Screw (pump cover) |
| 79 | 8302 | $ 3.5 | | Alfa carb/inlet manifold gasket |
| 80 | 7542 | $ 19.4 | | Pump non-return valve |
| 81 | 7509 | $ 6.1 | | Pump body gasket |
| 82 | 7550 | - | | DHLA45E Pump body |
| 83 | 7526 | $ 1.5 | | Pump body screw |
| 84 | 6416 | $ 2.2 | | Butterfly screw |
| 85 | 6449 | $ 5.4 | | DHLA48 choke retaining screw |
| 86 | 4957 | - | | Spring washer (choke screw) |
| 87 | 7151 | $ 8.2 | | Trumpet stud |
| 88 | 7957 | $ 5.7 | | Throttle return spring (std) |
| 88 | 8610 | - | | Throttle return spring (competition) |
| 89 | 6887 | $ 3.7 | | Cap screw |
| 90 | 8307 | $ 46.4 | | DHLA40 pump rod assy |
| 91 | 7507 | $ 7.2 | | Venturi grub screw |
| 92 | 3793 | $ 1.2 | | Split pin (balance lever) |
| 93 | 7496 | $ 6.8 | | Balance lever pin |
| 93 | 9752 | $ 6.8 | | Balance lever pin |
| 94 | 2638 | $ 1.7 | | Balance lever spring |
| 95 | 11529 | - | | Late Alfa balance lever |
| 96 | 7496 | $ 6.8 | | Balance lever pin |
| 97 | 6898 | $ 5.1 | | Throttle stop screw |
| 98 | 4670 | $ 1.7 | | Throttle stop screw spring |
| 99 | 4650 | - | | Washer |
| 100 | 8304 | $ 24.6 | | Lotus balance lever |
| 101 | 7668 | $ 58.9 | | DHLA 40 spindle |
| 102 | | - | | ?? |
| 103 | | - | | |
| 104 | ?? | - | | |
| 105 | | - | | ?? |