
WEBER 32/34 DFT

Exploded view



https://www.carbparts.eu

Les prix et la disponibilité des produits sont susceptibles de changer

WEBER 32/34 DFT

Liste des parties

No	Partie Non	Prix	Pcs	Description
1	Not Serviced	-	1	Top Cover Assembly
2	41565.008	-	1	Auto Choke O-Ring Seal
3	64565.001	-	3	Auto Choke Fixing Screw
4	57804.400	-	1	Auto Choke Assy. Including
5	47407.159	-	1	Choke Diaphragm
6	Not Serviced	-	1	Diaphragm Loading Spring
7	Not Serviced	-	1	Diaphragm Cover
8	Not Serviced	-	1	Diaphragm Adjusting Screw
9	Not Serviced	-	3	Diaphragm Cover Fixing Screw
10	64615.005	-	3	Plate Fixing Screw
11	52135.029	$ 2.7	1	Thermostat Housing Lock Ring
12	57804.416	-	1	Thermostat Housing
13	41640.056	-	1	Heat Sealing Gasket
14	Not Serviced	-	1	Screw Plug
15	41705.057	-	1	Carburetor Cover Gasket
16	41030.012	-	1	Float
17	77501	$ 7.5	2	Air Correction Jet
18	61450	$ 12	2	Emulsion Tube
19	52570.004	$ 10.1	2	Idle Jet Holder
20	74403	$ 3.8	2	Idle Jet
21	73405	$ 5	2	Main Jet
22	55510.087	-	4	Carb Washer
23	52130.010	$ 4.9	4	Shaft Bearing Plate
24	12750.085	$ 4.3	1	Spacer
25	10015.255	-	1	Secondary Shaft
26	52130.010	$ 4.9	4	Shaft Bearing Plate
27	Not Serviced	-	1	Secondary Throttle Adjusting Screw
28	55555.019	$ 1.7	2	Washer
29	Not Serviced	-	1	Throttle Valve Control Lever Including
30	64595.025	-	1	Fast Idle Adjusting Screw
31	34715.018	-	1	Adjusting Screrw Fixing Nut
32	55520.002	$ 1.1	2	Lock Washer
33	34715.014	$ 1.1	2	Primary Shaft Fixing Nut
34	47610.109	-	1	Bushing For Free Lever
35	45069.015	-	1	Free Lever
36	47610.109	-	1	Spring For Free Lever
37	12750.087	-	1	Spacer
38	Not Serviced	-	1	Primary Throttle Control Lever
39	47610.118	-	1	Primary Shaft Return Spring
40	Not Serviced	-	1	Primary Shaft
41	64005.090	$ 18	1	Primary Throttle Plate
42	64520.027	-	4	Throttle Plate Fixing Screw
43	47600.007	$ 2.6	1	Spring Primary Throttle Lever
44	64625.012	$ 8.2	1	Primary Throttle Adjusting Screw
45	10104.001	-	1	Dash Pot
46	Not Serviced	-	1	Dash Pot Bracket
47	34715.008	-	1	Dash Pot Fixing Nut
48	Not Serviced	-	1	Dash Pot Bracket Fixing Screw
49	41535.003	-	1	Idle Cut Off Solenoid Gasket
50	43840.014	-	1	Idle Cut Off Solenoid
51	Not Serviced	-	1	Mixture Screw Tamper Proof Plug
52	64750.051	$ 14	1	Idle Mixture Adjusting Screw
53	41565.001	-	1	Mixture Screw O-Ring Seal
54	47600.095	$ 2.8	1	Idle Mixrure Screw Spring
55	64565.001	-	4	Pump Cover Fixing Screw
56	Not Serviced	-	1	Pump Cover
57	47407.261	$ 11.1	1	Pump Diaphragm
58	47600.107	$ 9.4	1	Pump Loading Spring
59	47610.012	$ 5.1	1	Primary Shaft Return Spring
60	Not Serviced	-	1	Pump Cam
61	Not Serviced	-	3	Power Valve Cover Fixing Screw
62	Not Serviced	-	1	Power Valve Cover
63	47600.131	-	1	Power Valve Diaphragm Spring
64	47407.156	-	1	Power Valve Diaphragm
65	34705.001	-	1	Secondary Shaft Fixing Nut
66	55525.001	-	1	Spring Washer
67	Not Serviced	-	1	Washer
68	92.4052.05	-	1	EVAP Solenoid Includes
69	41535.009	-	1	Gasket
70	Not Serviced	-	1	Spring
71	Not Serviced	-	1	Spindle
72	Not Serviced	-	1	Sealing Valve
73	Not Serviced	-	1	Carburetor Body
74	41565.002	-	1	Pump Jet O-Ring
75	76407	$ 13.8	1	Pump Jet
76	71115	-	2	Auxiliary Venturi
77	79519	-	1	Needle Valve
78	52000.036	$ 2.1	1	Float Fulcrum Pin
79	37022.005	$ 6.3	1	Strainer
80	10525.032	-	1	Return Fuel Line Pipe
81	83102.070	-	1	Needle Valve Gasket
82		-		