




WEBER 40 DCZ

Exploded view



<https://www.carbparts.eu>

Los precios y la disponibilidad de los productos están sujetos a cambios



WEBER 40 DCZ

Lista de partes



No	Parte No	Precio	Pcs	Descripción
1	41530.004	-	2	Banjo Bolt Gasket
2	10602.001	-	1	Fuel Banjo Bolt
3	Not Serviced	-	1	Fuel Union
4	41530.031	-	1	Fuel Union Gasket
5	Not Serviced	-	1	Fuel Union Bolt
6	37022.001	\$ 23.1	1	Fuel Filter
7	Not Serviced	-	1	Fuel Union Cap
8	41530.001	\$ 2	1	Fuel Union Gasket
9	41705.011	\$ 16	1	Top Cover Gasket
10	83102.070	-	1	Needle Valve Gasket
11	Not Serviced	-	1	Pump Rod
12	79503	\$ 11.9	1	Needle & Seat
13	Not Serviced	-	1	Pump Rod Clip
14	Not Serviced	-	1	Pump Rod Spring
15	Not Serviced	-	1	Adjustment Tube
16	41030.003	-	1	Float
17	52000.001	\$ 2.4	1	Float Pin
18	79701	\$ 9.9	1	Exhaust Valve
19	58602.004	-	1	Plunger
20	74401	\$ 7.3	2	Idle Jet
21	52570.003	\$ 17.2	2	Jet Holder
22	41540.001	\$ 2	2	Main Jet Gasket
23	73801	\$ 4	2	Main Jet
24	52590.001	\$ 9.5	2	Jet Holder
25	64840.003	\$ 5	2	Locking Screw
26	61015.001	\$ 7.5	2	Plug
27	64590.003	\$ 6.8	2	Screw
28	Not Serviced	-	1	Carburetor Body
29	12750.251	-	1	Brass Spacer
30	58440.001	-	1	Roll Pin
31	47610.003	\$ 5.7	1	Spring
32	10016.409	-	1	Oversized Throttle Shaft
33	64005.057	\$ 19	2	Throttle Plate
34	64570.009	-	4	Throttle Plate Screw
35	10016.401	-	1	Oversized Throttle Shaft
36	47610.029	-	1	Spring
37	55520.001	\$ 1.7	2	Shaft Lock Tab
38	34715.01	-	2	Fixing Nut
39	45082.01	-	1	Pump Lever w/ Roller Wheel

No	Parte No	Precio	Pcs	Descripción
40	12750.04	-	1	Brass Spacer
41	58202.006	-	1	Throttle Shaft Gear
42	12800.076	\$ 29.3	1	Excentric
43	47600.007	\$ 2.6	2	Spring
43a	47600.007	\$ 2.6	2	Spring
44	Not Serviced	-	2	Spacer
45	64750.001	\$ 3.8	2	Idle Mixture Screw
46	Not Serviced	-	1	Lever Assembly
47	34705.002	-	1	Nut
48	Not Serviced	-	1	lever
49	Not Serviced	-	1	Washer
50	Not Serviced	-	1	Screw
51	Not Serviced	-	1	Cover
52	Not Serviced	-	1	Lever
53-a	4837A	-	1	Gear Clamp aluminum
53-b	4837B	-	1	Gear Clamp brass
54	64750.004	\$ 9.1	2	Screw
55	64605.001	-	1	Screw
56	64570.002	-	2	Screw
57	32610.005	\$ 1.6	1	Split Pin
58	Not Serviced	-	1	Clevis Pin
59	Not Serviced	-	1	Cold Start Bracket
60	47600.015	-	1	Spring
61	64370.001	-	1	Pin
62	64700.005	-	6	Top Cover Fixing Screw
63	61455	\$ 37.7	2	Emulsion Tube
65	77502	\$ 5.1	2	Air Corrector Jet
66	Not Serviced	-	1	Pump Jet
67	64290.005	\$ 34	1	Valve
68	41540.014	\$ 2.8	2	Pump Jet Gasket
69	Not Serviced	-	1	Air Valve
70	83101.150	-	1	Carb Gasket
71	Not Serviced	-	1	Drain Plug
72	71501	-	2	Main Venturi (Choke)
73	Not Serviced	-	2	Auxiliary Venturi
74	Not Serviced	-	1	Carb Top Cover Assembly
75	Not Serviced	-	1	Carb Top Cover
76		-		

<https://www.carbparts.eu>

Los precios y la disponibilidad de los productos están sujetos a cambios